



**Office of Environmental Public Health Sciences  
Washington State Department of Health  
243 Israel Road SE, Tumwater WA 98501**

**Lead Sample Collection Information**

**DISCLAIMER: Results posted here only represent testing done by the Washington State Department of Health for the 2018-19 lead in school drinking water program. Schools have been provided these results, along with recommendations for remediation if applicable. Please contact your school to find out more about this and other testing they may have done, as well as plans for remediation.**

**School Name:** Lakewood Middle School

**School Code:** 3893

**School District Name:** Lakewood

**Address:** 16800 16th Dr NE, Marysville WA 98271

**County:** Snohomish

**Date Collected:** 10/11/2018

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
1.	14832	First Draw	Bubbler	Outside 207	<1	10/17/2018	6:05AM
2.	14854	First Draw	Bubbler	Library Sink	1	10/17/2018	
3.	14874	First Draw	Tap	Library Sink	1	10/17/2018	
4.	14875	First Draw	Bubbler	Staff Lounge	5	10/17/2018	
5.	14876	First Draw	Tap	Staff Lounge	5	10/17/2018	
6.	14877	First Draw	Bubbler	Room 201	<1	10/17/2018	
7.	14878	First Draw	Tap	Room 201	<1	10/17/2018	No aerator
8.	14880	First Draw	Tap	Room 205	24	10/17/2018	No aerator, Low pressure
9.	14881	First Draw	Bubbler	Room 202	<1	10/17/2018	
10.	14882	First Draw	Tap	Room 202	<1	10/17/2018	
11.	14883	First Draw	Bubbler	Gym	1	10/17/2018	
12.	14884	First Draw	Tap	Nurses Office	1	10/17/2018	
13.	14885	First Draw	Tap	Concessions Sink	23	10/17/2018	
14.	14886	First Draw	Bubbler	Cougar Hall	37	10/17/2018	
15.	14887	First Draw	Tap	Room 403	21	10/17/2018	
16.	14888	First Draw	Bubbler	Room 404	16	10/17/2018	
17.	14889	First Draw	Tap	Room 404	6	10/17/2018	
18.	14890	First Draw	Bubbler	Room 207	27	10/17/2018	Left Side Sink
19.	14891	First Draw	Tap	Room 207	4	10/17/2018	Right Side Sink

Sample number	Sample ID	Sample Type	Fixture Description	Fixture Location	Lead Content (ppb)	Date of Analysis	Notes/Comments
20.	14789	First Draw	Bubbler	Outside 200 Building	10	10/17/2018	Outdoor Fountain
21.	14892	First Draw	Tap	Room 307	1	10/17/2018	Used by staff, Left Side Sink
22.	14893	First Draw	Tap	Room 307	2	10/17/2018	Right Side Sink, Bubbler turned off
23.	14894	First Draw	Bubbler	Room 308	1	10/17/2018	
24.	14895	First Draw	Tap	Room 308	2	10/17/2018	
25.	14896	First Draw	Bubbler	Room 301	2	10/17/2018	
26.	14897	First Draw	Tap	Room 301	1	10/17/2018	
27.	14898	First Draw	Bubbler	Across from Room 302	<1	10/17/2018	
28.	14899	First Draw	Bubbler	Room 302	3	10/17/2018	
29.	14900	First Draw	Tap	Room 302	<1	10/17/2018	
30.	14901	First Draw	Bubbler	Room 305	1	10/18/2018	Tap is turned off
31.	14902	First Draw	Tap	Room 304	1	10/18/2018	Bubbler turned off
32.	14903	First Draw	Bubbler	Room 303	2	10/18/2018	
33.	14904	First Draw	Tap	Room 303	2	10/18/2018	Very low flow, a trickle
34.	14905				<1	10/18/2018	03487, in Room 303